

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7A

HIGH VALVE LIFT




FIG.7B

LOW VALVE LIFT




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12




FIG.13A




FIG.13B




FIG.14





FIG.15



[illegible]

17

19

FIG.17




FIG.18




FIG.19




FIG.20A




FIG.20B




FIG.21

